

As mentioned, no expenses spared with the maintenance of this truck. Major work was done by Slee Off-Road, MainLine Overland in PA, State Automotive in Salt Lake City (the shop that Cruiser Outfitters works with, given they don't do installs anymore) and OLC 4x4 Chief Mechanic Bill Lee (which performed the last major maintenance).

I have all the paperwork from maintenance done by previous owners and myself.

***** The maintenance logs below are a copy & paste from the previous owner's sale ads (from 2014 to 2018 and 151k to 188k miles) *****

(From Johnny of OLC 4x4)

July 2014 @ 151,735

- Clean Car Fax
- Purchased in Colorado Springs from second owner
- OME torsion bars
- OME 860 rear springs
- OME Nitrocharger Shocks
- 16" LC wheels with 295/75-16 Nitto Terra Grapplers
- Slee Diff-drop
- Slee Sliders
- Slee Front Skid (aluminum)
- Slee Intermediate skid (aluminum)
- Slee Belly Skid (steel)

Baselined PM:

July 2014 @ 152,781

- Replace engine oil and filter (Mobil 1)
- Drain and fill differentials (Mobil 1)
- Drain and fill transfer case (Mobil 1)
- Drain and fill transmission (Mobil 1)
- Flush coolant
- Replace timing belt
- Replace spark plugs
- Replace CV shafts, boots and seals
- Alignment

July 2014 @ 152,911

- Replace Windshield

June 2015 @ 158,892 (work done at Camelback Toyota)

- Replace Upper Control Arms with SPC adjustable Upper Control Arms
- Replace lower ball joints with 555 (Japanese) ball joints

- Repack wheel bearings
- Replace steering rack (mild seeping from original unit's seals)
- Replace engine oil and filter (Mobil 1)
- Alignment

February 2016

- Replace battery with Batteries Plus Group 27F AGM

March 2016 @ 161,000

- BFG 295/75-16 KO2s (rotated and balanced every oil change)

May 2016 @ 162,876 (work done at Slee Off Road)

- ARB Front & Rear Air Lockers
- ARB CKMA12 Air Compressor
- 80 Series Locker Switch
- Replace Outer tie rod ends
- OME 868 rear springs
- SPC Rear Lower HD Control Arms with flex-joint
- Safari Snorkel
- ARB Winch Bar
- ARB LED marker lights
- Warn 9.5 XPs
- Slee Offset Fairlead
- Factor 55 Flatlink Expert winch thimble
- ARB LED High Intensity Lights (fog & spot) wired into OE harness
- Slee second battery tray/ARB compressor mount
- IBS Dual Battery System Controller
- IBS Remote Boost Module Kit
- Military Terminals on both batteries
- Interstate Group 35 AGM Battery as auxiliary (MT7-75DT)
- Slee Dual Pivot Rear Swingout with ladder and jerry can basket
- Replace Rear Driveshaft (slightly out of balance)
- Front and Rear Axle Seals
- Replace radiator hoses
- Replace coolant Ts
- Replace serpentine belt
- Replace engine oil and filter (Mobil 1)
- Alignment

May 2016 @ 163,757

- Maggiolina Grand Tour, medium (Like new, slept in 10 nights)
- Trekboxx Alpha Drawer, custom unit with 2 drawers on PS (thanks David!)

- ARB 63 Quart Fridge with Wits' End Coiled Power Cord (thanks Joey!)
- Blue-Sea 12 Circuit Negative Bus Fuse Block mounted in cargo area (4-gauge wire with 100 amp mega fuse to auxiliary battery)
- Marine LED Companionway Light and dual switched Marine USB ports at rear of drawer system
- H3R HalGuard 5 lb. Fire Extinguisher in H3R Extreme Duty Mount
- Front Runner Slimline Roof Rack
- Escape Gear Grey Canvas Seat Covers

January 2017 @ 167,981

- Replace engine oil and filter (Mobil 1)
- Lubricate Chassis and Suspension
- Complete Inspection
- Rotate and balance tires

May 2017 @170, 377

- Replace engine oil and filter (Mobil 1)
- Lubricate Chassis and Suspension
- Complete inspection
- Rotate and balance tires

September 2017 @177,190

- Replace engine oil and filter
- Replace air filter (OEM)
- Lubricate Chassis and Suspension
- Complete Inspection
- Rotate and balance tires

(From Ryan, previous owner before myself)

April 2018 @ 182k

- Replace engine oil / filter
- Replace rear drive shaft (dented old one, caused a vibration)
- Replace Front Diff fluid, Rear Diff Fluid, Transfer Case fluid
- Replace brake pads, bleed brakes
- Replace power steering fluid
- Replace coolant

June 2018 @ 188k

- Replace engine oil/filter
- Replace Air filter
- Replace Fuel Filter
- Replace Spark Plugs
- Replace Cabin Filter

***** From here on, those are my maintenance logs*****

April 2019 @ 192,585 (at MainLine Overland in PA)

- Replace engine oil and filter (Mobil 1)
- Drain and fill differentials (Mobil 1)
- Drain and fill transfer case (Mobil 1)
- Drain and fill transmission (Mobil 1)
- Flush Brake Fluid
- Replace CV axles, boots and seals (OEM)
- New Auxiliary Battery (Odyssey Group 34)
- Alignment
- Heater T's Replacement
- AT Propane Bracket install
- Eezi-Awn 2000 Series 2.0 Meter Awning install

Jun 2019 @ 195,395 (at RPM Offroad in TN)

- Replace Passenger side CV Axle (broken in a trail) (OEM)

Jul 2019 @ 199,356 (at Toyota Country Hills and Krave Automotive, both in Calgary, AB, Canada)

- Replace engine oil and filter (Mobil 1)
- Tire Rotation
- Full Inspection
- Swap Rear Brake Pads and Rotors (OEM)
- Replace Engine Air Filter (Self)

Sept 2019 @ 207,071

- Replace engine oil and filter (Mobil 1)
- Tire Rotation
- E-Brake Adjustment

Oct 2019 @ 211,458 (at State Automotive in Salt Lake City, UT)

- Replace Rear Upper Control Arm (HD adjustable)
- Install new OME Heavy Plus 3" Suspension Kit (purchased from CruiserOutfitters)
(http://www.cruiseroutfitters.com/sus_100series.html)
- Front Axle wheel bearing replacement
- Replaced both O2 Sensor upstream
- Replaced Front Brake Pads (Ceramic PowerStop)
- Replace Engine Air Filter (Self)

Nov 2019 @ 213,677

- Replace engine oil and filter (Mobil 1)

- Tire Rotation

Nov 2019 @ 214,094 (at Lynnwood Auto Rebuild)

- Rear Passenger side door replacement – please refer to “FULL DISCLOSURE” notice on original post

Dec 2019 @ 217,492 (at Mudrak Cruisers in CA)

- Replaced Starter (OEM / Denso)

- New Main Battery (X2 Power 27F SLI27FAGMDP)

Dec 2019 @ 218,221 (at Glendora Import in CA)

- Replaced Rear Brakes and Rotors (Akebono Ceramic Pads)

Jan 2020 @ 220,567 (at Bill Toys Shop – Bill Lee, Chief Mechanic of OLC 4x4)

- Replaced Timing Belt, Cam and Crank Seals

- Replaced Water Pump, Thermostat, Idlers, Pulleys, Tensioner, Fan Bracket

- Replaced Fuel Filter

- New Upper and Lower Ball Joints (SPC for Upper and 555 for Lower)

- Replaced Sway Bar Bushings (OEM)

- Pack spindle bearings and bushings

- Removed, lubed and balanced Rear Driveshaft and U-Joint

- Replaced Panhard Rod (OEM)

- Replaced Engine Mounts (OEM)

- Replaced Radiator Cap (OEM)

- Drain and fill Coolant

- Replaced Spark Plugs (Iridium)

- Replaced both O2 Sensors Downstream

- Replace engine oil and filter (Mobil 1)

- Drain and fill differentials (Mobil 1)

- Drain and fill transfer case (Mobil 1)

- Drain and fill transmission (Mobil 1)

- Drain and Fill Power Steering Fluid

- Replaced Cabin Air Filter

- Alignment

Feb 2020 @ 223,532

- Tire Rotation and Balance

Apr 2020 @ 226,056

- Lubed Rear U-Joints

- Replace Engine Oil and Filter (Mobil 1)

- Replace Engine Air Filter

Aug 2020 @ 228,278

- Replace Hoses and Clips of Power Steering Reservoir (OEM) – Hoses were starting to sweat
- Drain and Fill Power Steering Fluid
- Tire Rotation

Nov 2020 @ 232,199

- Replace Engine Oil and Filter (Mobil 1)
- Replace Engine Air Filter

Jan 2021 @ 233,267

- Tire Rotation